

Work Order ID 142015

Tuesday, February 23, 2016 2:23:22 PM

142015

Page 1

Item ID: D350-604-041 Accept ***N900040100*** Setup Start ***NS1***
 Revision ID: Stop ***NS2***
 Item Name: Rear Locker Extender
 Start Date: 2/23/2016 Start Qty: 1.00 ***1*** Cust Item ID:
 Required Date: 3/11/2016 Req'd Qty: 1.00 ***1*** Customer:
 Reference:

Approvals: Process Plan: MLJ Date: FEB 24 2016 Tooling: Date: Run Start ***NR1***
 QC: Date: SPC (Y/N): Date: Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr	DAS 10 9-89
D2273	<u>K L</u>	
D350-604-041	C	

MLJ 16-04-18

100 Document Control 0.00
100 DOCUMENT CONTROL
 DC Memo 0.00
 Doc.Control -USB or Paperwork Photocopy bluefile and create labels per PPP D350-604-041
 CHG009

DAS
27
9-89
APR 19 2016

110 PURCHASING 0.00
110 Purchasing Memo 0.00
 Purchasing Issue P/O: 31499
 Description: D350-604-041 Rear locker extender.
 Manufacture as per dwg D2273
 Supplier: FDC Composites Inc.
 Certification of Conformity and process sheet required.

DAS
13
9-89
FEB 25 2016

***EXTREME CARE MUST BE TAKEN TO PROTECT THE SURFACES OF
 THE REAR LOCKER. THE SURFACES MUST BE SMOOTH AND FREE
 FROM SURFACE DEFECTS SUCH AS SCRATCHES, NICKS, OR
 DENTS.***

MUST BE WELL PACKAGE, IF NOT IT WILL BE REFUSE

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition			
				Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
OTHER : ☐ _____					

Work Order ID 142015

Tuesday, February 23, 2016 2:23:22 PM

142015

Page 2

Item ID: D350-604-041

Accept

N900040100

Setup Start

NS1

Revision ID:

Item Name: Rear Locker Extender

Stop

NS2

Start Date: 2/23/2016 Start Qty: 1.00

1

Cust Item ID:

Required Date: 3/11/2016 Req'd Qty: 1.00

1

Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run Start

NR1

QC:

Date:

SPC (Y/N):

Date:

Stop

NR2Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID

Tool #

Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

120

Receive & Inspect for Damage & Mat'l Certs
Packaging

0.00

120

Packaging

Memo

0.00

Packaging

Ensure a copy of Certification of Conformity and process sheet from Carbon-by-Design is attached.

DO NOT STACK REAR LOCKERS OR ANYTHING ON THEM

DAS
6
9-89

APR 06 2016

130

QC6- Inspect dimensions to drawing

0.00

130

QC

Memo

0.00

Quality Control

Check hole locations to template. DT 8824 Check process sheet and audit.

① 16-04-27/14

DAS
9
9-89

140

0.00

140

Small Fab

Memo

0.00

Small Fab

1- INSTALL DECALS AS PER DWG

DAS
28
9-89

APR 19 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date :	Step #:	QTY Effective :		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition			
				Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
OTHER : ☐					

Work Order ID 142015

Tuesday, February 23, 2016 2:23:22 PM

142015

Page 3

Item ID: D350-604-041

Accept

N900040100Setup Start ***NS1***

Revision ID:

Item Name: Rear Locker Extender

Stop ***NS2***

Start Date: 2/23/2016 Start Qty: 1.00

1

Cust Item ID:

Required Date: 3/11/2016 Req'd Qty: 1.00

1

Customer:

Reference:

Approvals:

Process Plan: _____

Date: _____

Tooling: _____

Date: _____

Run Start ***NR1***

QC: _____

Date: _____

SPC (Y/N): _____

Date: _____

Stop ***NR2***Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID

Tool #

Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

150

QC5- Inspect part completeness to step on W/O

0.00

150

QC

Memo

0.00

Quality Control

27
9-89
APR 19 2016

155

Pick Kit

0.00

155

Packaging

Memo

0.00

Packaging

DO NOT STACK REAR LOCKERS OR ANYTHING ON THEM

158

QC4- 100% Inspect kits for completeness

0.00

158

QC

Memo

0.00

Quality Control

DAS
27
9-89
APR 19 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date :	Step #:	QTY Effective :		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition			
				Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
OTHER : ☐					

Work Order ID 142015

Tuesday, February 23, 2016 2:23:22 PM

142015

Page 4

Item ID: D350-604-041

Accept

N900040100Setup Start ***NS1***

Revision ID:

Item Name: Rear Locker Extender

Stop ***NS2***

Start Date: 2/23/2016 Start Qty: 1.00

1

Cust Item ID:

Required Date: 3/11/2016 Req'd Qty: 1.00

1

Customer:

Reference:

Approvals:

Process Plan: _____

Date: _____

Tooling: _____

Date: _____

Run Start ***NR1***

QC: _____

Date: _____

SPC (Y/N): _____

Date: _____

Stop ***NR2***Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID

Tool #

Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

160

160

Packaging

Packaging

0.00

Memo

0.00

Identify and pack for shipping as per PPP D350-604-041

Location: _____

PPP Rev: _____

fs107

DAS

27

9-59

APR 19 2016

170

170

QC

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

MCS APR 19 2016

Lm 16/04/19

MCS APR 19 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval		
Description Work Order Deviation				Disposition				Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐		Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐					
		OTHER : ☐							

Picklist Print

Tuesday, February 23, 2016 2:23:26 PM

Page 1

Work Order ID: 142015

142015

Parent Item: D350-604-041

D350-604-041

Parent Item Name: Rear Locker Extender

Start Date: 2/23/2016

Required Date: 3/11/2016

Start Qty: 1.00

Required Qty: 1.00

Comments: IPP Rev:Q03.12.01ReformatKJ/RF IPP REV:R
 12.02.07 AS PER ECN12-521 DD verf:JLM IPP REV:S 12.04.04
 AS PER DWG REV.B DD VERF:EC IPP REV:T 13.09.12 as per
 CHG006/ECN13-616 DDVERF:JLM IPP REV:U 14.05.28 as per
 chg008/ecn14-563 DD verf:JLM IPP REV:V 15.03.13 remove cam lock and
 washerDD verf:JLM IPP REV:W 15.03.25 ECN15-545 DD VERF:JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
---------------------------------	------------------------	---------------	-------------	---------------------	------------------	-----------------	--------------------	----------------	-------------	--------------	---------------	----------------	--------

D350-604-041P

Purchased

No

110

Each

0.0000

1

1

D350-604-041P

Rear Locker Extender

D2268

Manufactured

No

140

Each

13.0000

1

1

D2268

Placard

**

69-6
9
SVA

APR 06 2016

**

MLJ 16-04-18

Location

Loc Qty

Loc Code

ST006

13

130951

1

132546

12

D2728-1

Manufactured

Yes

140

Each

0.0000

1

1

D2728-1

Dart Logo Label Small

D2269

Manufactured

No

155

Each

20.0000

1

1

D2269

Placard

**

**

MLJ 16-04-18

Location

Loc Qty

Loc Code

ST006

8

131139

8

ST012a

12

135175

12

DAS
27
9-89

DAS
9-89

DAS
9-89

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition			
				Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
OTHER : ☐					

Picklist Print

Tuesday, February 23, 2016 2:23:26 PM

Page 2

Work Order ID: 142015

142015

Parent Item: D350-604-041

D350-604-041

Parent Item Name: Rear Locker Extender

Start Date: 2/23/2016

Required Date: 3/11/2016

Start Qty: 1.00

Required Qty: 1.00

D5062-041

Manufactured No

155

Each

19.0000

1

1

D5062-041

Bracket Assembly

MCS 16-04-18

Location

Loc Qty

Loc Code

ST147

19

130525

14

131060

5

CAS

27

9-89



DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval		
Description Work Order Deviation				Disposition				Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY							
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐				
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐				
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐				
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐				
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐				
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐				
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐				
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐				
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐				
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐				
Past Expiry Date ☐	Manufacturing Process ☐	OTHER : _____							
Misidentified ☐	Past Due ☐								

TABLE 1


POSITION	MATERIALS
1	TOOL SURFACE
2	GELCOAT
3	3/4 oz CHOPPED STRAND MAT
4	7725 FIBER GLASS
5	7725 FIBER GLASS
9	7725 FIBER GLASS
10	PRIMER

TABLE 2

POSITION	MATERIALS
1	TOOL SURFACE
2	GELCOAT
3	3/4 oz CHOPPED STRAND MAT
4	7725 FIBER GLASS
5	7725 FIBER GLASS
6	7725 FIBER GLASS
7	7725 FIBER GLASS
8	7725 FIBER GLASS
9	7725 FIBER GLASS
10	PRIMER

NOTES:

- 1) MATERIAL: SEE TABLE 3
- 2) FINISH: SEE TABLES 1, 2, & 3
ACCEPTABLE TO COVER CRACKS IN GELCOAT BY APPLYING A LAYER OF PPG 6941241A 2C ACRYCOTE WHITE PAINT OVER GELCOAT
- 3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) UNITS: INCHES UNLESS OTHERWISE NOTED
- 5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
- 6) IDENTIFICATION: IDENTIFY PER QSI 044 6.1
- 7) WEIGHT: 5.5- 7.5 lbs
- 8) LAMINATE PER DART QSI 006. LAMINATION SCHEDULE PER THIS DRAWING
- 9) LAYUP USING DT9871 MOLD. WET LAYUP WITH BAG/VACUUM
- 10) TRIM & DRILL PER DT9905. OPEN HOLES TO Ø0.257
- 11) CONSTRUCTION: SEE TABLES 1 & 2
- 12) MATTE TO HOLD DOWN CORNERS AS REQUIRED



D2273 REAR LOCKER EXTENDER

TABLE 3


MATERIAL USED	DESCRIPTION
GELCOAT	POLYCOR 2330PAWK745 (WHITE)
FIBER GLASS MAT	OWENS CORNING 3/4 oz CHOPPED STRAND MAT
FIBER GLASS CLOTH	HEXCEL 7725 FIBER GLASS
RESIN SYSTEM	DION 7704
PRIMER	TEMPO 4500-PB-23G (GREEN)

SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER

142015 MJS
16-02-24

SEE TABLE 1

SEE TABLE 2



SECTION A-A

L	ADD PAINT OPTION (NCR 15-5408)	CP	15.10.19
K	LAYUP AND MAT'L PER FDC COMPOSITES PROCESS	CP	15.03.12
J	CHANGED GELCOAT TO 4314-001 DURA FR WHITE	ML	13.12.10
I	CHANGE GELCOAT TO POLYCOR 2330PAWK745	SFM	13.08.13
H	CHANGE MATERIAL & MANUFACTURING PROCESS	DC	13.03.15
G	ADD MANUFACTURING OPTION B, ZN B5-1	DC	12.08.08
F	PRIMER LE 3404-S/LE 1175-S WAS 1144-S, ZN A6-1	DC	12.02.27
E	CHANGED SURFACE FINISH FROM 944W005 GELCOAT TO 2330PAWK745 GELCOAT, ZN A7-1. UPDATED DWG TO CURRENT STANDARDS.	DC	12.02.02
D	REMOVE EPOCAST, ADD SURFACE FINISH	CP	02.04.01
C	CLARIFY MATERIAL, LAYUP, AND TOOLING	RF	02.01.30
B	RE-DRAWN	MM	96.05.27
REV.	DESCRIPTION	BY	DATE

DESIGN	JB	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	CP		
CHECKED	AP	DRAWING NO.	REV. L
MFG. APPR.	JLM	D2273	SHEET 1 OF 1
APPROVED	WM	TITLE	SCALE
DE APPR.	DS	350 REAR LOCKER EXTENDER	NTS
DATE	15.10.19	COPYRIGHT © 1996 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	

RELEASED
2015-11-03
EN 15-637

APPROVED

DQA: _____ Date: _____




WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval 		
Description Work Order Deviation				Disposition					
							Completed By		
							Lead hand / Supervisor Approval Verification		
							QC / QA Coordinator Approval		
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐							
OTHER : ☐									

ITEM NO.	QTY.	PART NUMBER	DESCRIPTION
	X	D350-604-041	REAR LOCKER EXTENDER ASSEMBLY
1	1	D2268	PLACARD
2	1	D2273	REAR LOCKER EXTENDER
3	4	2600-6	CAMLOCK STUD
4	4	2600-LW	RETAINING WASHER



D350-604-041 REAR LOCKER EXTENDER ASSEMBLY

NOTES:

- 1) MATERIAL: N/A
- 2) FINISH: N/A
- 3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) UNITS: INCHES UNLESS OTHERWISE NOTED
- 5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
- 6) IDENTIFICATION: NONE
- 7) WEIGHT: 5.5 to 7.5 lbs
- 8) INSTALL D2268 PLACARD IN LOCATION SHOWN, CENTERED ON FLANGE

C	REMOVE D2728-1, D2729-1 DECALS (ZN C5-1). REVISED RELATED NOTES, UPDATED PART WEIGHT	ML	13.12.16
B	INCORPORATE DSI 9470 (ZN D7-1). UPDATE DWG TO CURRENT STANDARDS. ADD D2728-1 PLACARD AND ORIENTATION NOTE (ZN C3-1). ADD D2729-1 (ZN C5-1).	DC	12.02.07
A	NEW ISSUE	CP	02.04.01
REV.	DESCRIPTION	BY	DATE
DESIGN	DW	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	ML		
CHECKED	AP	DRAWING NO.	REV. C
MFG. APPR.	JLM	D350-604-041	SHEET 1 OF 1
APPROVED	MP	TITLE	SCALE
DE APPR.	DS	RLE ASSY	NTS
DATE	14.01.02	COPYRIGHT © 2002 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE, OR COPIED OR COMMENCED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	

APPROVED



Dart Aerospace Ltd.
1270 Aberdeen Street
Hawkesbury, ON K6A 1K7
Tel: 613 632 9577
Fax: 613 632 1053

PURCHASE ORDER

Purchase Order ID **PO31489**

Purchase Order Date 2/25/2016

PO Print Date 2/25/2016

Page Number 2 of 8

Order From : VC-FDC01
FDC COMPOSITES INC.
45 CHEMIN DE L'AEROPORT
LOCAL 26
ST-JEAN-SUR-RICHELIEU, QUEBEC J3B 7B5

Ship To : DART AEROSPACE LTD
1270 ABERDEEN
HAWKESBURY, ON K6A 1K7
CANADA

Contact Name
Vendor Phone 450-357-1344 ext303
Ship To Contact
Ship To Phone
Ship Via: Journey Freight collect
Ship Acct:

Buyer Chantal Lavoie
Customer POID
Customer Tax # 10127-2607
Terms Net 30
Currency CAD
FOB Destination-Collect

					Line Total:	\$835.00
4	D350-604-041P	Rear Locker Extender	3/23/2016 Yes 3/23/2016	1.00 Each	\$835.00	\$835.00
AS PER DWG.D2273 REV.L B141781					Line Total:	\$835.00
5	D350-604-041P	Rear Locker Extender	4/5/2016 Yes 4/5/2016	1.00 Each	\$835.00	\$835.00
AS PER DWG.D2273 REV.L B142014					Line Total:	\$835.00
6	D350-604-041P	Rear Locker Extender	4/5/2016 Yes 4/5/2016	1.00 Each	\$835.00	\$835.00
AS PER DWG.D2273 REV.L B142015						

Note:

2/25/2016

FDC Composites inc.
45, Chemin de L'Aéroport
Local 26
Saint-Jean-sur-Richelieu (QC)
J3B 7B5
Tél.: 450 357-1344

Bon de livraison

30/03/2016

Commande : 2406
Référence : PO #31489/1-8

Client : Dart

DART AEROSPACE
1270 Aberdeen Street
Hawksbury, ON
K6A 1K7

Expédier à

Même

Tél.: 1 613 632-9577

No item	Description	Qté	Qté livrée	Qté B/O
D350-604-041P	REAR LOCKER EXTENDER PO item: 31489/1 Lot: 2016-03-16-1 As per DWG.D2273 Rev .L B141778	1	_____	_____
D350-604-041P	REAR LOCKER EXTENDER PO item: 31489/2 2016-03-16-2 As per DWG.D2273 Rev .L B141779	1	_____	_____
D350-604-041P	REAR LOCKER EXTENDER PO item: 31489/3 2016-03-16-3 As per DWG.D2273 Rev .L B141780	1	_____	_____
D350-604-041P	REAR LOCKER EXTENDER PO item: 31489/4 2016-03-16-4 As per DWG.D2273 Rev .L B141781	1	_____	_____
D350-604-041P	REAR LOCKER EXTENDER PO item: 31489/5 2016-03-17-1 As per DWG.D2273 Rev .L B142014	1	_____	_____
D350-604-041P	REAR LOCKER EXTENDER PO item: 31489/6	1	_____	_____

*** Suite autre page ***

FDC Composites inc.
45, Chemin de L'Aéroport
Local 26
Saint-Jean-sur-Richelieu (QC)
J3B 7B5
Tél. : 450 357-1344

Bon de livraison 04/04/2016

Commande : 2406
Référence : PO #31489/1-8

Client : Dart

DART AEROSPACE
1270 Aberdeen Street
Hawksbury, ON
K6A 1K7

Expédier à

Même

Tél. : 1 613 632-9577

No item	Description	Qté	Qté livrée	Qté B/O
	2016-03-17-2 As per DWG.D2273 Rev .L B142015			
D350-604-041P	REAR LOCKER EXTENDER PO item: 31489/7 2016-03-17-3 As per DWG.D2273 Rev .L B142016	1		
D350-604-041P	REAR LOCKER EXTENDER PO item: 31489/8 2016-03-17-4 As per DWG.D2273 Rev .L B142017	1		

Page : 2

Transport : _____
Nb colis : _____
Marchandise reçue : _____

Réf. : _____



©The information in this document is FDC (Flight Dynamics Corp.) Proprietary Information and is disclosed in confidence. If you are not the intended recipient you are hereby notified that any disclosure, copying, distribution or use of any of the information contained in or attached to this transmission is STRICTLY PROHIBITED.

CERTIFICATE of CONFORMITY

Customer Name: Dart Aerospace.

Customer P/O Number: 31489

Rev. NC

<u>PO Item</u>	<u>Qty</u>	<u>Part number</u>	<u>Drawing number</u>	<u>Description</u>	<u>FDC ID</u>	<u>Lot</u>
1	1	D350-604-041P	D2273 Rev L	350 Rear Locker Extender	DAE001-066	2016-03-16-1
2	1	D350-604-041P	D2273 Rev L	350 Rear Locker Extender	DAE001-067	2016-03-16-2
3	1	D350-604-041P	D2273 Rev L	350 Rear Locker Extender	DAE001-068	2016-03-16-3
4	1	D350-604-041P	D2273 Rev L	350 Rear Locker Extender	DAE001-069	2016-03-16-4
5	1	D350-604-041P	D2273 Rev L	350 Rear Locker Extender	DAE001-070	2016-03-17-1
6	1	D350-604-041P	D2273 Rev L	350 Rear Locker Extender	DAE001-071	2016-03-17-2
7	1	D350-604-041P	D2273 Rev L	350 Rear Locker Extender	DAE001-072	2016-03-17-3
8	1	D350-604-041P	D2273 Rev L	350 Rear Locker Extender	DAE001-073	2016-03-17-4


NOTE :

Paint process : interior surface re-painting as specified on Darts's PO by sanding gelcoat to remove cracks and application of PPG 6941241A 2C Acrycote White paint Lot 01516. Catalyst was PPG 794002 2C Acrycote Lot 98841.

Catalysed PPG acrycote paint complies with FAR 25.853 Appendix F Part I (b)-Par.4 (Vertical Test 60 seconds).

I hereby certify that the workmanship, material and the processes used in the manufacture of the above part(s) supplied are in accordance with the requirements of the applicable Purchase Order.

Signature:


Jules Fournier, BDI, Quality Manager

Date: 2016-03-30